

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt PO Box 145801 Governor

Kathleen Clarke **Executive Director**

Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 Salt Lake City, Utah 84114-5801 801-538-5340

801-359-3940 (Fax)

801-538-7223 (TDD)

INSPECTION REPORT

| Partial: XXX | Complete:_ | Exploration: | D |
|--------------|------------------|--------------------------|-----|
| Inspection | Date & Time: | 01/16/2001 / 9:30am-2:00 |)pm |
| | st Inspection: _ | | |

| Mine Name: <u>Deer Creek Mine</u> County: <u>Emery</u> Permittee and/or Operator's Name: PacifiCorp | Permit Number: | | | | | | |
|---|-------------------|--|--|--|--|--|--|
| Business Address: P.O. Box 310, Huntington, Utah 84528 | | | | | | | |
| Type of Mining Activity: Underground XXX Surface | Prep. Plant Other | | | | | | |
| Company Official(s): <u>Dennis Oakley</u> | - | | | | | | |
| State Official(s): Stephen J. Demczak Federal Official(s): None | | | | | | | |
| Weather Conditions: 6"-8" snow cover, cold | | | | | | | |
| Existing Acreage: Permitted 17,826.85 Disturbed 95.79 | Regraded Seeded | | | | | | |
| Status: Active XXX | _ | | | | | | |

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For <u>partial inspections</u> check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

| | | EVALUATED | N/A | COMMENTS | NOV/ENI |
|-----|---|-----------|--------|-----------------|---------|
| 1. | PERMITS, CHANGE, TRANSFER, RENEWAL, SALE | [X] | | [X] | |
| 2. | SIGNS AND MARKERS | | \Box | П | |
| 3. | TOPSOIL | | П | П | |
| 4. | HYDROLOGIC BALANCE: | | | | |
| | a. DIVERSIONS | [X] | \Box | [X] | \Box |
| | b. SEDIMENT PONDS AND IMPOUNDMENTS | [X] | \Box | [X] | |
| | c. OTHER SEDIMENT CONTROL MEASURES | П | \Box | \Box | \Box |
| | d. WATER MONITORING | [X] | Ш | [X] | \Box |
| | e. EFFLUENT LIMITATIONS | \Box | | \Box | \Box |
| 5. | EXPLOSIVES | | \Box | \prod_{i} | |
| 6. | DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES | . [] | \Box | \Box | |
| 7. | COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS | [X] | | [X] | |
| 8. | NONCOAL WASTE | [X] | \Box | [X] | \Box |
| 9. | PROTECTION OF FISH, WILDLIFE AND RELATED | | | | |
| | ENVIRONMENTAL ISSUES | \Box | \Box | \Box | \Box |
| 10. | SLIDES AND OTHER DAMAGE | \Box | | \Box | \Box |
| 11. | CONTEMPORANEOUS RECLAMATION | \Box | \Box | \Box | \Box |
| 12. | BACKFILLING AND GRADING | \Box | \Box | \Box | \Box |
| 13. | REVEGETATION | \Box | \Box | \Box | |
| 14. | SUBSIDENCE CONTROL | [X] | \Box | [X] | \Box |
| 15. | CESSATION OF OPERATIONS | | \Box | | \Box |
| 16. | ROADS: | | | | |
| | a. CONSTRUCTION/MAINTENANCE/SURFACING | | \Box | | \Box |
| | b. DRAINAGE CONTROLS | \Box | \Box | \Box | \Box |
| 17. | OTHER TRANSPORTATION FACILITIES | \Box | \Box | \Box | |
| | SUPPORT FACILITIES/UTILITY INSTALLATIONS | [X] | \Box | [X] | |
| | AVS CHECK (4th Quarter- April, May, June) | \Box | \Box | П | \Box |
| 20. | AIR QUALITY PERMIT | \Box | \Box | П . | \Box |
| 21. | BONDING & INSURANCE | [1] | [] | [] | [] |

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/015/018

DATE OF INSPECTION: 01/16/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee is in the process of responding to the Division in regards to deficiencies within the Deer Creek reclamation plan amendment #AM99C.

4A. HYDROLOGIC BALANCE: DIVERSIONS

Several diversions were spot-checked and complied with the R645 Coal Rules. No water was flowing during the inspection. Some of the diversions were filled with snow.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond at the mine was inspected with no hazardous conditions noticed. The sediment pond at the waste rock site was not discharging.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The permittee has not sent the lab results to the Division at this time. The permittee will send the information electronically. This will be the first time for the permittee. The permittee will be taking water samples for first quarter where it is accessible.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The active waste rock pile was inspected with no hazardous conditions noticed. The area was covered with snow.

8. NONCOAL WASTE

The mine site was basically free of non-coal waste material.

14. SUBSIDENCE CONTROL

The permittee will be submitting the subsidence information in the Annual Report.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

There were no new surface facilities added since the last inspection.

Inspector's Signature:

Stephen J. Demczak

Date: January 19, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM

Chuck Semborski, PacifiCorp

Price Field office

O:\015018.DER\Compliance\2001\p 0116.wpd